

No. 10-05-02-01R/01

SYSTEM: Space Shuttle RSRM 10 CRITICALITY CATEGORY: 1 SUBSYSTEM: Assembly Hardware/Interfaces PART NAME: Case-to-Nozzle Joint, Subsystem Metal Components (1) Case-to-Nozzle Interface 10-05-02 ASSEMBLY: PART NO: (See Section 6.0) 10-05-02-01R Rev M Boost (BT) FMEA ITEM NO.: PHASE(S): CIL REV NO.: M (DCN-533) QUANTITY: (See Section 6.0) DATE: 10 Apr 2002 EFFECTIVITY: (See Table 101-6) SUPERSEDES PAGE: 351-1ff. HAZARD REF.: BC-04 DATED: 31 Jul 2000 CIL ANALYST: B. A. Frandsen APPROVED BY: DATE: RELIABILITY ENGINEERING: K. G. Sanofsky 10 Apr 2002 ENGINEERING: ___ B. H. Prescott 10 Apr 2002 1.0 FAILURE CONDITION: Failure during operation (D) 2.0 FAILURE MODE: 1.0 Structural failure of metal components 3.0 FAILURE EFFECTS: Failures of components would result in the expulsion of the nozzle and instantaneous thrust increase followed by large thrust decrease causing loss of RSRM, SRB, crew, and vehicle 4.0 FAILURE CAUSES (FC): FC NO. DESCRIPTION **FAILURE CAUSE KEY** Nonconforming materials 1.1 Α 1.2 В Cracks, voids, or other material defects 1.3 Nonconforming heat treatment С 1.4 Contamination and/or corrosion D 1.5 Stress corrosion Ε F 1.6 Nonconforming dimensions 1.7 In-service degradation and/or fatigue G 1.8 Improper assembly techniques Н 1.9 Transportation, handling, or assembly damage

DOC NO. TWR-15712 VOL III

SEC 351 PAGE 1

J

Damaged threads

1.10



DATE: 10 Apr 2002
No. 10-05-02-01R/01 SUPERSEDES PAGE: 351-1ff.
DATED: 31 Jul 2000

5.0 REDUNDANCY SCREENS:

SCREEN A: N/A SCREEN B: N/A SCREEN C: N/A

6.0 ITEM DESCRIPTION:

1. Nozzle-to-Case joint metal components consist of the nozzle fixed housing and the aft case segment (Figures 1 and 2). Materials are listed in Table 1.

TABLE 1. MATERIALS

========	=======================================	.==============	========	=======
Drawing No.	. Name	Material	Specification	Quantity
1U76034	Bolt, Case/Nozzle	Inconnel 718	AMS 5662 QQ-P-416	100/motor
1U75167	Bolt, Machine	MP35N Alloy	AMS 5844 QQ-P-416	99/motor 01/motor
	Fastener, Cadmium Plated		STW3-1533	A/R
1U77640	Segment, Rocket Motor, Aft			1/motor
1U76887	Pin, Spring	CRES 420	MS16582	1/motor
1U76794	Case Segment, Aft, Forging	D6AC Steel	STW4-2606, STW7-2608	1/motor
1U50129	Dome. Aft			1/motor
	Steel, Alloy, High	D6AC Steel	STW4-2606	
1U75642	Case Assembly, Painted Aft Dome	Various		1/motor
8U50800	Shipping Kit-Segment			A/R
	Helical-Coil Inserts	302/304 Corrosion-Resistant Steel	NASM33537	A/R
	Sealing Compound	Synthetic Rubber, Polysulfide	STW5-9072	A/R

6.1 CHARACTERISTICS:

1. The entire nozzle assembly is attached to the motor case through the Fixed Housing Assembly. It is attached to the case by means of 100 bolts in the fore-aft direction and 100 bolts in the circumferential plane and the joint is sealed with O-rings and Stat-O-Seals. This joint is provided with a leak check port and vent port that are closed after test with plugs (Figures 1 and 2).

7.0 FAILURE HISTORY/RELATED EXPERIENCE:

1. Current data on test failures, flight failures, unexplained failures, and other failures during RSRM ground processing activity can be found in the PRACA database.

8.0 OPERATIONAL USE: N/A

DOC NO. TWR-15712

SEC



No. 10-05-02-01R/01

DATE: 10 Apr 2002 SUPERSEDES PAGE: 351-1ff. 31 Jul 2000 DATED:




Figure 1. Case-to-Nozzle Joint, Metal Components Location

TWR-15712 DOC NO. SEC

351

REVISION M (DCN-533)

PAGE 3



No. 10-05-02-01R/01

DATE: 10 Apr 2002 SUPERSEDES PAGE: 351-1ff. DATED: 31 Jul 2000




Figure 2. Case-to-Nozzle Joint, Metal Components

DOC NO. TWR-15712 | VOL III | SEC | 351 | PAGE 4



DATE: 10 Apr 2002 No. 10-05-02-01R/01 SUPERSEDES PAGE: 351-1ff. 31 Jul 2000 DATED:

9.0 RATIONALE FOR RETENTION:

9.1 DESIGN:

<u>CN</u>	FAILURE CAUSES		
	A	1.	The nozzle fixed housing and aft case segment are made from a low-alloy, high-strength D6AC steel. Chemical composition, mechanical properties, and metallurgical characteristics for each component are per engineering.
	A,D	2.	Spring pins are corrosion resistant steel (CRES) 420.
	A,B,C,D,E,F,G	3.	Structural analyses per TWR-16975 show that all metal components of the joint have a positive margin of safety based on factors of safety of 1.4 on ultimate and 1.1 on yield.
	В	4.	The aft case segment and nozzle fixed housing are metal parts that are designed to specific loads and safety factors and are additionally designed for reuse. TWR-16875 provides justification for reuse and criteria for acceptance of RSRM components. Controls in this program are per engineering and provide justification for reuse of parts containing cracks, voids, or other material defects.
	В	5.	The aft case segment and nozzle fixed housing are heat treated for high strength and high toughness with reduced internal and surface stresses per engineering.
	A,C,G	6.	The nozzle to case joint axial bolt is heat treated steel. Specific requirements are for tensile and yield strength per engineering.
	A,C,G	7.	Radial bolt Material is alloy steel that is heat treated per AMS specifications.
	C,G	8.	The basic forging was analyzed per JSC Specification SE-R-0006 and the results reported in TWR-10719 for the Fixed Housing. This report shows the forging to be free of re-entrant or sharply folded lines and that the principal grain flow is oriented parallel with principal stresses expected.
	D	9.	All metal surfaces of the nozzle fixed housing are protected from corrosion per engineering.
		10.	Aft case segment surfaces are inspected for contamination, and cleaned as necessary.
	D		a. During processing, Thiokol takes steps to protect all case segment exposed bare metal surfaces to minimize corrosion. Superficial discoloration is allowed as long as it does not interfere with inspection of the hardware.
	D		 Corrosion is removed prior to hardware assembly per engineering. During local transportation, Thiokol uses environmentally controlled shipping containers which allow case segments to be shipped without grease per TWR-65920.
	D D		 c. Case segments are painted with primer and top coat. d. Filtered grease is applied to sealing surfaces prior to assembly.
	D	11.	Contamination control requirements and procedures are per TWR-16564.
	D,E,G	12.	Refurbishment of the nozzle fixed housing is per engineering drawings and specifications.
	D	13.	The indexing pin is made from alloy steel that has excellent corrosion resistance.

VOL III



		CRITICAL ITEMS LIST (CIL)		
		No. 10-05-02-01R/01 DATE: 10 Apr 2002 SUPERSEDES PAGE: 351-1ff. DATED: 31 Jul 2000		
D,E	14.	Refurbishment of the Aft Case Segment is acceptable per engineering.		
D	15.	Radial bolts are made from alloy steel per AMS specifications, that has excellent corrosion resistance.		
D	16.	Nozzle-to-Case joint axial bolts are made from alloy steel that has excellent corrosion resistance.		
D	17.	Nozzle-to-case joint radial and axial bolts are refurbished per engineering.		
D	18.	Protection of sealing surfaces, O-rings, and leak check port threads from damage and contamination during handling and shipment is provided by installed protective plugs per shop planning.		
Е	19.	Stress-corrosion resistance characteristics of D6AC steel, coupled with residual stress tests, support the conclusion that stress corrosion does not present a problem to the current design per TWR-12718.		
	20.	The heat-treat process of tempering reduces surface and internal stresses:		
C,E,G		 The nozzle fixed housing is a heat treated D6AC steel forging per engineering. 		
C,E,G		 b. The aft case segment is fabricated from D6AC steel and heat treated per engineering. 		
E	21.	A stress test report describes development test methods used to determine residual stresses in D6AC steel. From the test data, it is concluded the maximum tensile stress is less than the stress corrosion cracking threshold per TWR-12718.		
E	22.	Nozzle to case joint radial and axial bolts are made of materials listed in the MSFC specification which are alloys with high resistance to stress corrosion cracking, therefore, a Material Use Agreement is not required.		
Е	23.	A Material Use Agreement is required for the Aft Segment and Fixed Housing per MSFC specifications.		
E,F	24.	Stress analysis for maximum allowable dimensional pre-assembly mismatch is per TWR-17118. Stress analysis for the effects of plastic yielding during hydro-proof testing is per TWR-17118. Stress corrosion of mismatched components is per TWR-16873.		
Е	25.	Bolts are cadmium plated per Federal Specifications.		
Е	26.	Relief from hydrogen embrittlement is accomplished by baking.		
F	27.	Aft Case Segment dimensions are per engineering.		
F	28.	Nozzle fixed housing dimensions are per engineering drawings.		
F,G	29.	Nozzle-to-case joint axial bolt dimensions are per engineering drawings. These bolts are reused.		
F,G	30.	Radial bolt dimensions are per engineering drawings. These bolts are reused.		
F	31.	Refurbished nozzle fixed housing dimensions are per engineering drawings and specifications.		
F	32.	Refurbished Aft Case Segment dimensions are per engineering.		



		CRITICAL ITEMS LIST (CIL)	DATE:	40 4 0000
		No. 10-05-02-01R/01	DATE: SUPERSEDES PAGE: DATED:	10 Apr 2002 351-1ff. 31 Jul 2000
G	33.	TWR-16873 and TWR-16875 provide analysis in Case Segments and Nozzle Fixed Housing.	determining servic	e life of the
Н	34.	An indexing pin on the Nozzle, Fixed Housing positioning as the Nozzle Fixed Housing and Aft TWR-10341.		
Н	35.	Snug torque values, installation sequence, and an radial bolts of the Nozzle-to-Case Joint are per method was qualified per TWR-66211 and TWR-66	engineering. The	
Н	36.	Corrosion-preventive compound is filtered to control	contamination.	
Н	37.	Guide pins are used to aid in assembly of the planning.	Nozzle-to-Case Joi	nt per shop
I	38.	Shop procedures are developed to minimize errors Nozzle components are tagged "program critical hat the Thiokol IHM 29.	during handling an ardware" per shop բ	d assembly. lanning and
I	39.	Requirements for handling RSRM components of transportation are similar to those for previous a Thiokol. These requirements dictate RSRM case of near a joint to avoid damage. All lifting hooks a hooks per TWR-13880.	and other current pegments must be h	orograms at andled by or
I	40.	Positive cradling or support devices and tie down weight, and contour of components to be transp RSRM segments and other components. Shock devices are used on trucks and dollies to move sense.	oorted are provided mounting and other	I to support er protective
I	41.	The nozzle assembly is shipped in the Aft Segment and vibration levels are monitored per engineering a by analysis. Monitoring records are evaluated by vibration levels per MSFC specification SE 019-049 16975 documents compliance of the nozzle vispecifications.	and applicable loads by Thiokol to verify I-2H were not excee	are derived shock and eded. TWR-
I	42.	Protection of leak check vent port threads from dar handling is provided by installed protective plugs. when leak tests are performed and flight plugs performed to verify no transportation or handling dar	Protective plugs a are installed. Inst	are removed
1	43.	Analysis is conducted by Thiokol engineering to a response of the RSRM nozzle during transportation launch sites per TWR-16975.		
J	44.	Aft Dome internal threads at the Case-to-Nozz requirements for new and refurbished Aft Domes have no damage or defects greater than that calle are inspected after proof testing.	per engineering.	Threads will
J	45.	New and refurbished Aft Domes are proof tester threads are loaded in this test.	d per engineering.	Aft Dome
J	46.	Thread damage repair requires Discrepancy Repo action per engineering. Helical inserts may be us		



10 Apr 2002 DATF: SUPERSEDES PAGE: 351-1ff. No. 10-05-02-01R/01 DATED: 31 Jul 2000

performing tests to assure the twenty-use requirement and structural capability of helical inserts in D6AC steel per TWR-18555.

A,B,C,D,E,F,G

47. Analysis of carbon-cloth phenolic ply angle changes for the nozzle was performed. Results show that redesigned nozzle phenolic components have a reduced inplane fiber strain and wedge-out potential per TWR-16975. New loads that were driven by the Performance Enhancement (PE) Program were addressed in TWR-73984. No significant effects on performance of the RSRM nozzle were identified due to PE.

533 A,B,C,D,E,F,G

48. Thermal analysis per TWR-17219 shows the nozzle phenolic meets the new performance factor equation based on the remaining virgin material after boost phase is complete. This performance factor will be equal to or greater than a safety factor of 1.4 for the fixed housing assembly per TWR-74238 and TWR-75135. (Carbon phenolic-to-glass interface, bondline temperature and metal housing temperatures were all taken into consideration). The new performance factor will insure that the CEI requirements will be met which requires that the bond between carbon and glass will not exceed 600 degree F, bondline of glass-tometal remains at ambient temperature during boost phase, and the metal will not be heat affected at splashdown.

A,B,C,D,E,F,G

REVISION M (DCN-533)

49. TWR-61410 was updated to include boundary conditions created by the Performance Enhancement (PE) Program. This report analyzed temperature conditions created from flight loads. PE temperatures are equal to current generic temperatures for all locations for the critical time of liftoff. For a few locations at the factory joints and case acreage during flight, temperatures rise, but only slightly, and maximum case temperatures are lower than current generic certification. For flight load events, PE temperatures are not significantly different from current generic temperatures. There is no impact on previous analyses or margins of safety for the case membranes, factory joints, and field joints per TWR-61410.

> DOC NO. 351



DATE: 10 Apr 2002 No. 10-05-02-01R/01 SUPERSEDES PAGE: 351-1ff. DATED: 31 Jul 2000

9.2 TEST AND INSPECTION:

FAILURE	CAUSES and
TEOT	/ T \

DCN TEST	<u>(T)</u>	<u>CIL CODE</u>
----------	------------	-----------------

1. For New Housing, Nozzle-Fixed verify:

A,C A,C A,C A A A	(T) (T) (T) (T) (T) (T) (T)	a. b. c. d. e. f. g.	Chemical composition Elongation Fracture toughness (K _{IC}) Grain size Inclusion rating Macro structure Reduction in area	ADV018 ADV063 ADV073 ADV133 ADV135 ADV134 ADV171
A,C	(T)	ĥ.	Ultimate tensile strength	ADV213
A,C	(T)	i.	Yield strength	ADV229
B,E,G	(T)	j.	Magnetic-particle	ADV113
B,E,G	(T)	k.	Ultrasonic	ADV222
B,E,G	(T)	l.	Hydroproof test	ADV097
С		m.	Material	ADV195
С		n.	Heat treat	ADV085
D		0.	Grease application	ADV090
D		p.	Corrosion protection is per	specification ADV090
F		q.	Thickness	ADV034,ADV034A,ADV035,ADV035A
		-		ADV204,ADV205,ADV207,ADV208
F		r.	Flatness	ADV039,ADV040,ADV042,ADV043
F		S.	Diameter	ADV048,ADV049,ADV053,ADV054,ADV055,ADV057
F		t.	Height	ADV069,ADV070
F	(T)	u.	Hydroproof test	ADV097
F		٧.	Profile	ADV154,ADV155
F		W.	Run out	ADV178,ADV179
F		Χ.	True position	ADV210A,ADV211,ADV212,ADV212A

2. For Refurbished Housing, Nozzle-Fixed verify:

B,E,G	(T)	a.	Hydroproof test	ADV092
D		b.	Surfaces cleaned	ADV029
E,G	(T)	C.	Magnetic-particle	ADV110
F		d.	Thickness	ADV033
F		e.	Diameter	ADV050,ADV058
F		f.	Height	ADV071
F		g.	Straightness	ADV152
F		ĥ.	Roundness	ADV176,ADV180,ADV182
F		i.	Flatness	ADV197
G		j.	Painted surfaces for heat degradation	ADV082

3. For New Case Segment, Aft, Forging, verify:

A,C	(T)	a.	Elongation after heat treatment	AAJ055,AAJ058
A,C	(T)	b.	Ultimate strength, uniaxial, after heat treatment	AAJ174,AAJ175
A,C	(T)	C.	Fracture toughness after heat treatment	AAJ065,AAJ068
A,C	(T)	d.	Reduction in area after heat treatment	AAJ006,AAJ153
A,C	(T)	e.	Yield strength after heat treatment	AAJ201,AAJ204
A,C	(T)	f.	Chemical composition (D6AC)	AAJ021
B,E	(T)	g.	Ultrasonic inspection of the forging	AAJ177
F		h.	Wall thickness near clevis	AAJ195,AAJ196
F		i.	Wall thickness near Datum -G-	AAJ198,AAJ199
F		j.	Wall thickness at point B	AAJ016,AAJ192

PAGE 9



			CRITICAL ITEMS LIST (CIL)		
			No. 10-05-02-01R/01	DATE: SUPERSEDES PAGE: DATED:	10 Apr 2002 351-1ff. 31 Jul 2000
		4.	For New Bolt, Case/Nozzle verify:		
	(T) (T)		 a. Mechanical properties b. Chemical composition c. Material d. Diameter of bolt shank e. Length dimension f. Length of grip g. Threads h. Circular run out of bolt bearing surface i. Fillet role radius area 	AGE01 AGE01 AGE01 AGE02	AGE010 AGE003 AGE020 08,AGE009 12,AGE013 15,AGE016 18,AGE019 26,AGE027 32,AGE033
		5.	For Refurbished Bolt, Case/Nozzle verify:		
B D,G F			a. Surface defectsb. Part is acceptablec. Threads		AGE006 AGE034 AGE017
		6.	For New Bolt, Machine verify:		
	(T) (T)		 a. Ultimate tensile strength b. Material and chemical composition c. Part is acceptable d. "L" dimension e. "B" diameter f. Threads g. Run out between Datum -A- and Datum -B- h. Circular run out of bolt bearing surface i. "R" radius 	AEIO AEIO AEIO AEIO	AEI040 AEI018 AEI501 010,AEI011 006,AEI007 016,AEI017 031,AEI032 024,AEI025 027,AEI028
		7.	For Refurbished Bolt, Machine verify:		
B D,G F			a. Surface defectsb. Part is acceptablec. Threads		AEI004A AEI501 AEI015
		8.	For New Pin, Spring, Tubular, Slotted verify:		
	(T) (T)		 a. Chemical properties b. Mechanical properties c. Correct material (CRES 420 or carbon steel as require engineering) 	ed per	AJS000 AJS002 AJR001
		9.	For New Insert, Helical Coil, verify:		
Α			a. Material is corrosion resistant steel		RHB001
		10.	For New Case Segment, Aft, verify:		
B,E,G,J B,E,F,G,J F F F F F	(T) (T)		 a. Magnetic particle inspection after hydroproof test b. Hydroproof test c. Inner clevis leg wall thickness d. Outer clevis leg wall thickness e. Flange thickness at Datum -G- f. True position of aft boss threaded holes g. Depth of threads in aft boss threaded holes h. Tap drill depth of aft boss threaded holes 	AAJ146 AAJ0 AAJ1 AAJ0	AAJ114 AAJ078 2,AAJ092A 5,AAJ146A 60,AAJ061 69,AAJ170 38,AAJ039 36,AAJ167



				CRITICAL ITEMS LIST (CIL)		
				No. 10-05-02-01R/01 S	ATE: UPERSEDES PAGE: ATED:	10 Apr 2002 351-1ff. 31 Jul 2000
F			i.	Flatness of Datum -G-	ΔΔ.ΙΟ	62,AAJ063
F			j.	Diameter of Datum -A-		40,AAJ041
F			k.	Diameter of Datum -F-		43,AAJ044
F			I.	Run out of Datum -F-		RAA207
F			m.	Clevis pin hole diameter),AAJ026A
J	(T)		n.	Axial and radial threaded bolt holes are eddy-current in		
				after hydroproof, and all non-conforming conditions are	е	A A 1054
1			^	dispositioned Depth of threads in aft boss threaded holes	۸۸۱0	AAJ051 38,AAJ039
J J			0. p.	Tap drill depth of aft boss threaded holes		36,AAJ167
Ĵ			q.	Axial and radial threaded holes with Go-No-Go gauge		00,7 0 10 101
			-1	hydroproof		AAJ010
J			r.	True position of aft boss threaded holes	AAJ1	69,AAJ170
		11.	For	Refurbished Case Segment, Aft, verify:		
D = 0 1	(T)			11. 1		A A 1075
B,E,G,J	(T)		a.	Hydroproof test Magnetic-particle inspection after hydroproof test		AAJ075 AAJ105
E,G,J D	(T)		b. C.	Surfaces are cleaned to remove foreign material and o	corrosion	AAJ103 AAJ030
F			d.	Case wall thickness	2011031011	FAA587
F			e.	Inner clevis leg wall thickness		AAJ093
F			f.	Outer clevis leg wall thickness		AAJ147
F			g.	Clevis sealing surface gap		AAJ028
F			h.	Axial and radial threaded holes with Go-No-Go gauge	after hydroproof	AAJ011
F F			i.	Clevis pin hole diameter		AAJ025
F J	(T)		j. k.	Diameter of inner boss Axial and radial threaded bolt holes are eddy-current in	nenacted	AAJ042
J	(1)		ĸ.	after hydroproof, and all non-conforming conditions are		
				dispositioned	C	RAA208
J			l.	Axial and radial threaded holes with Go-No-Go gauge	after hydroproof	AAJ011
		12.	For	New Segment Assembly, Rocket Motor, verify:		
D,H			a.	Aft Segment and Fixed Housing holes are clean and fi	ree from	
_				debris and foreign material prior to assembly		AGJ007
D			b.	Fixed Housing vent ports and leak check ports are cle	aned and	A C 1022
D			C.	free from foreign material Aft Segment Boss and Fixed Housing Aft end holes ar	e free from	AGJ023
D			О.	damage including scratches, pits, galls, and burrs prio		
				assembly		AGJ104
D			d.	Fixed Housing aft end leak check port is free from dan	nage prior	
				to installation of the leak check port plug		AGJ015
D			e.	Fixed Housing aft end vent port is free from damage p	rior to	4010454
D			£	installation of the Adjustable Vent Port Plug		AGJ015A
D D			f. g.	Sealant is applied around bolt heads Sealant is applied around joint seam		AGJ215 AGJ216
D,I			h.	Leak check vent ports have protective plugs installed		AGJ210 AGJ148
Б,. Н			i.	Axial bolts are torqued in proper sequence prior to lea	k test	AGJ076
Н			j.	Radial Bolt, Machine is torqued to proper specification		
				leak test		AGJ211
H			k.	Radial bolts are torqued in proper sequence prior to le		AGJ210
Н			l.	Fixed Housing surface by black light inspection for pro	per grease	A C 1400
ш			m	application Proper location of all holts		AGJ120 AGJ205
H H	(T)		m. n.	Proper location of all bolts Axial and Radial bolts are tightened with a snug torque	e and	AGJZUO
••	(')		•••	angle-of-twist		AGJ238
Н			0.	Axial bolts are coated with lubricant on grips and unde	er heads	AGJ075
Н			p.	Radial bolts are coated with lubricant on grips and unc		AGJ209

REVISION M (DCN-533)

DOC NO. TWR-15712

VOL III



		No. 10-05-02-01R/01	DATE: SUPERSEDES PAGE: DATED:	10 Apr 2002 351-1ff. 31 Jul 2000
Н		q. Molykote spray lubricant is applied to the threads of bolts and air dried before installation per the proce		
н		 specification Molykote spray lubricant is applied to the threads of bolts and air dried before installation per the process. 		LHA047
D,H		s. Application of lubricant to aft dome axial and radia	al surfaces	LHA048 BAA600
	13.	For New Case Assembly, Aft Dome, Painted verify:		
D D		a. Shelf life and environmental history, paint and primb. For application of paint and primer, facilities and environmental history.		90,FAA091
D D		clean c. For application of paint and primer, humidity and c d. Surfaces to be primed are clean and free from con		FAA092 FAA098 FAA097
D D D		 e. Container is covered after mixing, paint and primer f. Full cover coat, paint and primer g. Runs, sags, drips, and inclusions are acceptable p 	FAA0	99,FAA100 93,FAA094
D		specification, paint and primer h. Dry film thickness, paint and primer	FAA	095,FAA096 01,FAA102
	14.	For Shipping Kit-Segment, verify:		
I		a. Transportation EDR data is acceptable		RAA232
	15.	KSC verifies:		
I		 Segments and nozzle components are free of dam OMRSD File V, Vol I, B47SG0.061. 	nage per	OMD079

DOC NO. TWR-15712 | VOL III | PAGE 12